



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
March 29, 2011

Reviewed: 

Mine Name: Coyote Knoll 1-2-3	Permit Number: S/023/0086
Operator Name: Mc Farland & Hullinger	Inspection Date: 03/24/2011
Inspector(s): Wayne Western	Time: 11:30 AM - Noon
Other Participants: none	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The Division gave conditional approve for transferring the permit from McFarland & Hullinger Company to Desert Mound Gold Inc. on March 14, 2011. The transferee must post a bond and sign the reclamation contract.


The highwalls at the site are near vertical and will have to be brought to a 1H to 1V slope at reclamation.

There is a water tank at the site along with a well. There is some minor amount of used equipment that should be removed.

Conclusions and Recommendations:

The Division should continue to inspect the site on an annual basis.

Inspector's Signature

A handwritten signature in blue ink, appearing to read "Wayne Gese", written over a horizontal line.

whw

CC: McFarland & Hullinger
BLM-Fillmore-Jerry Mansfield

O:\M023-Juab\S0230086-CoyoteKnoll\inspections\Insp03242011.doc



Edge of pit looking north



Pit looking north



Pit looking north east



Pit looking west